

BIOFA Universal Hartöl (Universal Hard Oil) Art. No. 2044

Properties

High-quality universal hard oil made from natural raw materials. It freshens the natural texture, deepens the shade of the treated substrates and provides an open-pored, satin finish, hard-wearing, **dirt- and** water-repellent, largely yellowing-resistant finish. The universal hard oil is suitable for absorptive surfaces inside such as wooden, linoleum and cork floors, staircases, **furniture**, Sterling OSB boards and interior fittings.

Ingredients

Aliphatic hydrocarbons, ricinen oil, colophonium resin ester, safflower oil, silicon dioxide, swelling clay, micro wax, zinc oxide, **succinic acid ester**, cobalt, zirconium and manganese octoate dryer, antiskinning agent.

Instructions for use:

1. Pretreatment

Substrates must be dry (max. **12%** wood moisture), clean, absorptive and free of grease. If necessary, clean with BIOFA Verdünnung (Thinner) 0500. Remove old coatings. Carry out final sanding with grit size 240 on furniture, with grit size 120 on floors.

2. Basecoat

Stir well and apply thinly and evenly by brush, roller, spraying, dip coating or wiping. Preferably use a short-pile velour roller in floor areas. Prime very absorptive substrates or substrates whose natural colour shall be brought out with BIOFA Universal Hartgrund (Universal Hard Primer) 3755 or alternatively with solvent-free BIOFA Parkettöl spezial (Special Parquet Oil) 2059. The minimum floor temperature during the application is 16°C.

3. Intermediate coat and topcoat

Carry out intermediate sanding (150-180 grit abrasive mesh for floors, grit size 240 for interior fittings) after the first hard primer or hard oil application.

Treat wooden and cork floors **at least** 2 x with BIOFA Hartöl. When using BIOFA Hartöl on its own, apply 2-3 thin layers depending on the substrate's absorbency. The first coat can also be applied by padding. If necessary, carry out respective intermediate sanding. If surfaces turn out uneven, apply another hard oil layer. Surfaces are only fully stress-resistant in the case of sufficient film formation and thickness. **Important: Carry out a preliminary test! Provide optimum fresh air circulation during product application and drying!**

Spraying data

Spray application:

Cup spray gun with compressed air: 1 - 1.5 mm nozzle, 2 - 2.5 bar spray pressure.

Airless: 0.23 - 0.28 mm nozzle, 4 bar spray pressure, 80 bar material pressure.

4. Cleaning of tools

Clean with BIOFA Verdünnung (Thinner) 0500 immediately after use.

5. Cleaning and maintenance of surfaces

Dry cleaning with a soft broom, cloth, mop or vacuum cleaner brush. Damp cleaning with a pH-neutral, mild cleaner in hand-hot water. We recommend NACASA Universalreiniger (Universal Cleaner) 4010 (BIOFA dealer). See special maintenance instructions for floor surfaces!

Drying

BIOFA Universal Hartöl is dust dry after 6-12 hours, sandable and recoatable after 16-24 hours (20°C / 50-55 % rel. air humidity).

Floors are resistant to minor stress after 3 days, fully stress resistant after 7-14 days.

Low temperatures, high air and surface humidity and use on wood containing tannic acid, tropical wood and cork may slow down the drying process.

Consumption/spreading rate

1st coat: approx. 60 - 80 ml/m² or 12 - 16 m²/l.
2nd and 3rd coat: 45 - 60 ml/m² or 16 - 20 m²/l each. Consumption and spreading rate strongly

The data and information provided in this technical data sheet are binding. If it is necessary to deviate from these provisions, the Application Technology Department of BIOFA must be consulted in advance. The general rules for structural engineering are to be complied with. With publication of this technical data sheet all previous data sheets regarding this product are no longer valid.

depend on the substrate's absorbency and nature.

Waste Code according to European Waste Catalogue: 08 01 11*

Storage

Cool, dry and sealed airtight. Skin formation is possible. Remove skin prior to use. If necessary, sieve oil.

GISCODE: Ö 60

Container size

0.25 l / 0.75 l / 2.5 l / 10 l / 30 l metal containers.

Safety instructions

Attention! Store work materials such as rags, sponges, clothes, sanding dust, etc. soaked with the product in airtight metal containers or rinse, spread and allow to dry on non-inflammable surface (**risk of spontaneous ignition!**). The product itself is not self-igniting, but inflammable. "Contains cobalt octoate and butanonoxime. May cause allergic reactions." Toxic to aquatic organisms. May cause long-term adverse effects in the aquatic environment. Keep out of the reach of children. Do not breathe vapour/aerosol. Only use in well ventilated areas. Avoid release to the environment. Refer to special instructions/safety data sheets. Provide for sufficient skin protection during the application. **Wear fine dust respirator when sanding!** The natural raw materials used may cause type-specific odour!

Disposal

Dispose of liquid product residues at collection points for old paints/varnishes or dispose of according to locally applicable regulations. Small quantities of residue and soaked work materials can be disposed of along with domestic waste after drying.

Only recycle cleaned or completely empty packaging with cured deposits or dispose of according to locally applicable legal regulations. Uncleanable packaging and packaging not emptied appropriately must be treated and disposed of like the product!

VOC identification according to Decopaint Directive and ChemVOCFarbV (Directive on the limitation of emissions of volatile organic compounds due to the use of organic solvents in paints and varnishes):

EU limit value (cat. A/e): 500 g/l (2007)

2044 contains max. 490 g/l VOC.

The data and information provided in this technical data sheet are binding. If it is necessary to deviate from these provisions, the Application Technology Department of BIOFA must be consulted in advance. The general rules for structural engineering are to be complied with. With publication of this technical data sheet all previous data sheets regarding this product are no longer valid.